

Diver-Mate

Bluetooth

- Connected to phone
- ⦿ Transferring Diver data to phone

Battery


- 100...40 %
- ⦿ Less than 40 %
- Charging
- Fully charged
(when connected to USB)

USB

- Connected to PC
- ⦿ Connecting

USB-C connector

Plug the Diver-Mate into a PC or power bank for charging



Memory

- OK
- Error

DXT Cable Signal Quality

- Good
- ⦿ Fair

Diver Data Download

- Finished
- ⦿ Busy
- Error

DXT Cable connector